SERGE BARIL HST

TEE SPLICE KIT

FOR TYPE FPS & CCA SELF-REGULATING HEATER CABLES

INSTALLATION INSTRUCTIONS

DESCRIPTION


The HST Tee Splice is for use with metal braid versions of Serge Baril type FPS and CCA self-regulating heater cables in ordinary areas.

KIT CONTENTS


- 10 Insulated Splice Connectors
- 5 Uninsulated Splice Connectors
- 5 152mm (6") length Shrink Tubes
- 5 Mastic Strips
- 5 Wire Ties

STRIPPING PROCEDURES


For Braided "B" Products proceed to step 4 below.



- Lightly cut around heater outer jacket 89mm (3.5") from the end. Bend cable to break outer jacket.
- 2 Lightly cut overjacket up the center between first cut mark and the cable end. Bend cable to break overjacket.




3 Remove overjacket from heater cable.



Move braid back toward the overjacket, creating a bulge.



6 At the bulge, separate the braid to make an opening.



6 While bending heater cable, work it through the braid opening.



- Pull braid tight.
- 8 Repeat steps 1-7 for the other 2 heater cables.
- Proceed to "Outer Jacket Stripping Procedures", Sheet 2 of 3.




SERGE BARIL HST

TEE SPLICE KIT


FOR TYPE FPS & CCA SELF-REGULATING HEATER CABLES

INSTALLATION INSTRUCTIONS


OUTER JACKET STRIPPING PROCEDURES




- Lightly cut around heater outer jacket 51mm (2") from the end. Bend cable to break outer jacket.
- 2 Lightly cut the outer jacket up the center between the first cut mark & cable end. Bend cable to break the outer jacket.




3 Remove jacket from the heater cable.



Starting at the end, pull each bus wire away from the core material.



- **6** Remove exposed core material.
- Proceed to "Shrink Tube Procedures", sheet 3 of 3.



4 Shave the core material from the outside of each bus wire.


SERGE BARIL HST

TEE SPLICE KIT


FOR TYPE FPS & CCA SELF-REGULATING HEATER CABLES

INSTALLATION INSTRUCTIONS

SHRINK TUBE PROCEDURES




Position three heater cables with the ground braid on the same side. Remove 32mm (1.25") of bus wire from each heater cable to offset for the insulated splice connectors.




2 Slide one 13mm (0.5") diameter, 152mm (6") length shrink tube over the single heater cable side. Twist bus wires together from the two heater cables and crimp into insulated splice connectors, then connect to the single heater cable. Place a mastic strip between the two heater cables forming a moisture harrier.

*For Overjacket "BA" Products only:

Slide one 16mm (0.63") diameter, 229mm (9") length shrink tube over the two heater cables side. *See diagram above*.




3 Center the 13mm (0.5") diameter, 152mm (6") length shrink tube over the connectors leaving the braid straps exposed. Make sure the shrink tube covers the mastic strip. Shrink with heat gun until completely shrunk. A uniform bead of glue should appear around the ends of the shrink tube. Fasten a wire tie around the two heater cables to hold in place.



If necessary, cut excess length from braid straps. Crimp the braid straps together into an uninsulated splice connector. Secure connector at the indented area with one and a half wraps of fiberglass tape (not included in kit).

*For Overjacket "BA" Products only:



Center the 16mm (0.63") diameter, 229mm (9") length shrink tube over the splice and braid connection. Shrink with heat gun until completely shrunk. A uniform bead of glue should appear around the ends of the shrink tube.

SERGE BARIL & ASS. INC.

5310 des Laurentides Blvd., Laval, Canada H7K 2J8 Tel: (450) 622-7587 Fax: (450) 622-7869

